

INSPECTOR NOTE

Building:	TRA6
Street:	HINDLE ROAD
Suburb:	BRENTWOOD PARK
Postal Code:	
Date:	2026-08-18
Time:	16:58
Inspector:	LWAZI NTUNGELE
Type:	CASE DISCUSSION NOTE
Follow-Up Date:	2026-08-20
Comments:	As per inspector prins, I whatsapp the complainant but no response on her whatsapp will follow-up on Thursday again
Captured By:	LWAZI NTUNGELE 2026-08-18 16:58